YODER ★ SMOKERS

COMPETITION GRADE BBQ PRODUCTS

Technical Service Bulletin

Date: 12-15-2015   **TSB#** 000004

Release Date: **12-15-2015**

Models: **YS480 all styles**

Effective Serial Number: **22127**

Type: Firmware Update to R37 (YS480)

Description

It was brought to our attention by some users that there could be a temperature differential between grate and the displayed value. We verified that we could recreate this behavior. We corrected the temperature off set to center grate. This resulted in the release of R37 in all current YS480 models.

Corrective Action

Flash all effective units that are R35 or R36 with R37.

This programming will not work on any cooker that is currently running R34 due to the difference in thermocouple size and location.

We will ship programmers on request, in date order, after the filled out and signed authorization form is returned to us. Click here for the Programmer Authorization Form

If you purchased your pit from a dealer please contact them to receive the programmer.

For further information or questions, please send an email to Customerservice@yodersmokers.com or call 877.409.6337 option 2

Customer Support Forum: http://community.yodersmokers.com