



Technical Service Bulletin

Date: 04-23-2015

TSB# 000001

Release Date: 04-22-2015

Models: YS480, YS640 all styles

Effective Serial Number: 19196

Type: Firmware Update to R36 (YS480) and U28 (YS640)

Description

We recently discovered a failure in our testing equipment that collects temperature profile data. This data is used to create the temperature profile to operate the pellet smoker. Once the temperature variations were discovered, we immediately updated our test equipment. The result is the release of R36 and U28 to replace R35 and U27 on all pits.

Corrective Action

Flash all effective units that are R35 or U27 with R36 or U28. This programming will **not** work on any cooker that is currently running R34 or U26 due to the difference in thermocouple size and location.

We will ship programmers on request, in date order, after we receive the signed authorization form back.

If you purchased your pit from a dealer please contact them to receive the programmer.

For further information or questions, please send an email to Customerservice@yodersmokers.com or call 877.409.6337 option 2

Customer Support Forum: <http://community.yodersmokers.com>