



## Technical Service Bulletin

**Date:** 10-21-2015

**TSB#** 000003

**Release Date:** 10-16-2015

**Models:** YS640 all styles

**Effective Serial Number:** 21269

**Type:** Firmware Update to U29 (YS640)

### Description

It was brought to our attention by some users that there could be a temperature differential between grate and the displayed value. We verified that we could recreate this behavior. We corrected the temperature off set to center grate. This resulted in the release of U29 in all current YS640 models.

### Corrective Action

Flash all effective units that are U28, with U29 firmware.

**This programming will not work on any cooker that is currently running U26 due to the difference in thermocouple size and location.**

We will ship programmers on request, in date order, after the filled out and signed authorization form is returned to us. Click here for the [Programmer Authorization Form](#)

If you purchased your pit from a dealer please contact them to receive the programmer.

For further information or questions, please send an email to [Customerservice@yodersmokers.com](mailto:Customerservice@yodersmokers.com) or call 877.409.6337 option 2

Customer Support Forum: <http://community.yodersmokers.com>